

SUBJECT: LOAD TEST 50 AMPS 34044-5
AUTHOR: FRED SAUER
TECHNICIAN: FRED SAUER
REPORT NO: ENG-05-NOV-2020-1
DATE: 05/11/2020


- **Part Description:**

34044-5-000 PCB Rev B and Rev C




- **Equipment List:**

High current test fixture. 80TK Thermocouple Module, Multimeter, Espec test chamber

- **Test Setup:**



• Results:

<p>Ran a series of output load tests on two 34044-5 PCBs. Both had been tested and calibrated on the PAT factory test.</p> <p>PC xtremDB tool showing settings and snapshot of data.</p>	
<p>Amp readings for first unit. Rev B PCB.</p>	
<p>Amp readings for the second unit. Rev C PCB.</p>	
<p>Additional test for the second unit. Added five amps to the load bank.</p>	