element

Data sheet
Vibration

Company name	Data Panel	**Performed by**	LRS	**Pages**	1 of 11
Job number	52911	**Specification**	DSGN-4015-S Para 1.2.3		
DUT description	DP Block and Mini Combo	**Test date(s)**			

Device under test information

Description	Model / part number	Serial number
Shock	34044-3	Dut 1,2,3

Equipment list

Fixture number	Plate 10” x 18” x 1”	Control accelerometer	480-138 C1	Signal condition	
Control system	503-217A	Monitor accelerometer		Signal condition	
Exciter	503-221	Accelerometer		Signal condition	
Amplifier	503-221	Accelerometer		Signal condition	

Axis	Hz	Level	Duration	Graph number	Test	Date
X-Axis		50g	11ms +3 -3	0701-0006	Mechanical Shock	03/15/2016
Y-Axis		50g	11ms +3 -3	0740-0006	Mechanical Shock	03/17/2016
Z-Axis		50g	11ms +3 -3	0928-0006	Mechanical Shock	03/21/2016

Test results

No damage noted after completion of vibration testing.

Disposition	|( )| Retained at Element Minneapolis	|(X)| Returned to customer	|( )| Other (describe):

The data provided herein is FOR PRELIMINARY USE ONLY, and has not been reviewed or approved by Element Minneapolis quality system for accuracy or completeness.